



QTY





REQUIRED TOOLS

Jack Stands or Lift Mig Welder Paint/Primer Hand Grinder Cutting Wheel or Torch Welding Gloves Welding Hood/Shield Ear & Eye Protection Sockets & Ratchet Fire Extinguisher Paint Marker

KIT CONTAINS

Rear Cab Mount	1
M10 Flanged Hex Screw	2

RB7123L & RB7123R



1) PREPARING YOUR VEHICLE

Begin by disconnecting your battery prior to starting your installation.

Inspect your vehicle for leaking fuel lines, fuel tank and engine components. If you have fuel leaks repair all leaks prior to starting your installation. If your fuel tank is near your welding area **remove your tank prior to welding.**

Remove all combustible items above the work area such as seats, carpets, padding, etc.

Keep all flammable materials away from the vehicle work area.

2) PREPARING YOUR WORKSTATION

Keep a fire extinguisher close by in the case of fire and make sure you always have a designated "Fire Watch" to assist during the cutting or welding phases.

Abide by all apprenticed welding safety standards and practices.

Always use appropriate welding eye protection, ear protection, and work and fire safety gloves during the installation and within the work area.



If you are unsure on how to perform the installation or how to operate any of the required tools listed above, it is **HIGHLY** advised that you enlist the work of a certified welder/installer.

Failure to follow proper safety precautions and instructions may result in serious injury. **The user assumes all liability when installing the product.**



3) PREPARING FOR YOUR INSTALL

Jack up your vehicle. With a 13mm socket, remove your body mount bolt and bushing.

4) **CUT**

Cut off the factory rear cab mount.





Grind the frame free of rust and debris, revealing bare metal.



Spray the work area with a weldable primer to help prevent against rust development.



Using the silhouette where the factory body mount was originally located, hold the part up to the frame and mark off its coverage using a paint marker.







5) WELD

Following proper welding procedures, tac weld the rear cab mount onto the frame before welding it on fully. Weld 100% around all edges.



6) PAINT

Paint the part with primer or other rust inhibitor to help prevent or reduce the risk of rust formation.

We recommend our Rust Buster Rust Converter & Primer Spray Paint (RB9917).



7) **REINSTALL**

Using a 13mm socket, reinstall your body mount and bushing.

